

SAIC
Science Applications International Corporation
An Employee-Owned Company
Technology Services Company

RECEIVED

MAR 26 1993

Superfund Response & Investigation Branch

March 25, 1993

DCN: TZ4-C10025-LR-13250

Mr. Dave Bennett
U.S. Environmental Protection Agency
1200 Sixth Avenue (HW-113)
Seattle, WA 98101

Subject: SIP Report for Zilog, Inc. in Nampa, Idaho
W.A. C10025, EPA No. 68-W9-0008
SAIC/TSC Project No. 6-788-03-1408-170

USEPA SF



1643303

Dear Mr. Bennett:

A file review for Zilog, Inc. has been completed. Based on this review, we are unable to document a source of contamination to use in completing the HRS score. Therefore, an HRS score is not being prepared for this facility.

SITE BACKGROUND

Zilog, Inc. has operated since 1979 at 2515 11th Avenue North in Nampa, Idaho. The facility is a RCRA generator that manufactures integrated circuits. Wastes are stored onsite temporarily and then shipped to an approved TSD facility. The EPA I.D. number is IDD097762231.

Wastes include arsenic trioxide, liquid mercury compounds, trichloroethane, and acetone. Over 392 tons of waste have been generated over an eight year period. Several violations have been issued over the years including labeling, record keeping, storage, and transportation.

AREAS OF CONCERN

Currently there are no areas of concern at Zilog, Inc. Historically, there have been two areas of concern under CERCLA: the potential for leaks and spills from drums and the potential for leaks from the onsite underground waste acetone storage tank. Although there are several RCRA Inspections that document labeling, storage, and handling violations, there is no documentation that demonstrates that spills have actually occurred. A similar situation exists for the underground storage tank. Several violations have been issued over the years for

Mr. Dave Bennett
March 25, 1993
Page 2 of 2



inadequate inspection of that tank. There is no documentation of any leaks from that tank.


NEW INFORMATION

In September 1990, the underground acetone tank was removed and replaced with an aboveground tank with secondary containment. Soil surrounding the 11 year old tank was sampled and analyzed. The removal and cleanup was found to be adequate by the Idaho Department of Health and Welfare on November 2, 1990.

Please feel free to call Lynn Guilford or me at (206) 485-2818 if you have any questions or comments regarding this submittal.

Sincerely,

Technology Services Company, A Division of
SCIENCE APPLICATIONS INTERNATIONAL CORPORATION



Louis Craig
Environmental Scientist

Enclosure:

cc: G. Sink (letter only)
P. Rubenstein (letter only)